Issues

| # | Project | Tracker | Status | Priority | Subject | Assignee | Updated | Category |
|----|------------|---------|----------|----------|--|----------|------------------|-----------------------|
| 65 | LAOS Laser | Feature | Closed | Normal | Show the outline of the drawing | | 2014-08-17 20:38 | |
| 16 | LAOS Laser | Feature | Closed | Low | Binary distribution of the CUPS-Laos driver and PSTOEDIT for windows, Linux and MAC | | 2014-08-17 20:59 | CUPS |
| 56 | LAOS Laser | Bug | Closed | Normal | Delete all files from SVN, and make binaries available via github | peter | 2013-02-24 19:33 | Documentation |
| 80 | LAOS Laser | Bug | Closed | High | Use other transport instead of TFTP | | 2014-08-17 17:41 | firmware |
| 64 | LAOS Laser | Bug | Closed | Normal | Make jogging and origin work as expected | | 2014-08-17 17:45 | firmware |
| 14 | LAOS Laser | Feature | Closed | Normal | Change laser PWM control: rewrite using own PWM function | | 2014-08-17 20:42 | firmware |
| 66 | LAOS Laser | Bug | Closed | High | Laser is ON at boot | peter | 2014-08-17 01:01 | firmware |
| 43 | LAOS Laser | Bug | Closed | Normal | Make Laos compile on GCC4MBED | peter | 2012-12-29 16:40 | firmware |
| 52 | LAOS Laser | Bug | Closed | Normal | Decoupling of the stepper drives | jaap | 2012-11-24 15:53 | Mainboard |
| 48 | LAOS Laser | Bug | Closed | Normal | More information on the silkscreen | jaap | 2012-11-24 15:55 | Mainboard |
| 15 | LAOS Laser | Feature | Closed | Low | Stand-alone CUPS-laos server on openWRT or RaspberyPi | | 2014-08-17 17:53 | Printserver |
| 57 | LAOS Laser | Bug | Closed | High | Printing from Inkscape via CUPS driver generates incorrect lines (sub-paths not handled correctly) | jaap | 2012-11-24 15:52 | pstoedit |
| 55 | LAOS Laser | Bug | Closed | Normal | Delete old wiki | jaap | 2013-03-16 07:25 | Website |
| 54 | LAOS Laser | Feature | Rejected | Normal | pull-up resistors on PWM opto out signals | | 2012-12-05 22:45 | Auxiliary Electronics |