Issues

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Category
96	LAOS Laser	Bug	Closed	Normal	mbed.patch not compatible with latest mbed version		2014-08-17 21:21	
95	LAOS Laser	Bug	Closed	Normal	VERSION_STRING not updated in compilation?		2014-08-17 17:37	
94	LAOS Laser	Bug	Closed	High	Can't control speed anymore?		2014-08-17 17:38	
86	LAOS Laser	Bug	Closed	Normal	Better acceleration algorithm		2014-08-17 17:40	firmware
85	LAOS Laser	Bug	Closed	Normal	Lasering long vertical line at start of jobs after the first job	peteruithoven	2013-06-02 14:38	
84	LAOS Laser	Bug	Closed	Normal	Joystick thumb		2013-05-11 21:42	
83	LAOS Laser	Bug	Closed	Normal	Move not limited / end stops not working?		2013-05-09 00:42	firmware
82	LAOS Laser	Bug	Rejected	Normal	Non-Pololu only assembly unclear?		2013-05-08 22:20	Documentation
81	LAOS Laser	Bug	Closed	Normal	Wiki: Missing image	peteruithoven	2013-05-11 21:18	Documentation
79	LAOS Laser	Feature	Closed	Normal	Adding WYSIWYG to website		2014-08-17 17:49	Website
78	LAOS Laser	Bug	Closed	Normal	Use Frequency from VisiCut		2014-08-17 17:42	
77	LAOS Laser	Bug	Closed	Normal	Have to send job twice?		2014-08-17 17:44	firmware
76	LAOS Laser	Bug	Closed	Normal	wiki PWM unclear, please clarify.	hugomeiland	2013-03-11 12:12	Documentation

2025-05-17