

Issues

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Category
80	LAOS Laser	Bug	Closed	High	Use other transport instead of TFTP		2014-08-17 17:41	firmware
66	LAOS Laser	Bug	Closed	High	Laser is ON at boot	peter	2014-08-17 01:01	firmware
64	LAOS Laser	Bug	Closed	Normal	Make jogging and origin work as expected		2014-08-17 17:45	firmware
57	LAOS Laser	Bug	Closed	High	Printing from Inkscape via CUPS driver generates incorrect lines (sub-paths not handled correctly)	jaap	2012-11-24 15:52	pstoedit
56	LAOS Laser	Bug	Closed	Normal	Delete all files from SVN, and make binaries available via github	peter	2013-02-24 19:33	Documentation
55	LAOS Laser	Bug	Closed	Normal	Delete old wiki	jaap	2013-03-16 07:25	Website
52	LAOS Laser	Bug	Closed	Normal	Decoupling of the stepper drives	jaap	2012-11-24 15:53	Mainboard
48	LAOS Laser	Bug	Closed	Normal	More information on the silkscreen	jaap	2012-11-24 15:55	Mainboard
43	LAOS Laser	Bug	Closed	Normal	Make Laos compile on GCC4MBED	peter	2012-12-29 16:40	firmware
65	LAOS Laser	Feature	Closed	Normal	Show the outline of the drawing		2014-08-17 20:38	
54	LAOS Laser	Feature	Rejected	Normal	pull-up resistors on PWM opto out signals		2012-12-05 22:45	Auxiliary Electronics
16	LAOS Laser	Feature	Closed	Low	Binary distribution of the CUPS-Laos driver and PSTOEDIT for windows, Linux and MAC		2014-08-17 20:59	CUPS
15	LAOS Laser	Feature	Closed	Low	Stand-alone CUPS-laos server on openWRT or RaspberyPi		2014-08-17 17:53	Printserver
14	LAOS Laser	Feature	Closed	Normal	Change laser PWM control: rewrite using own PWM function		2014-08-17 20:42	firmware