

LAOS Laser - Bug #47

Random artifacts on bitmap jobs

2012-09-29 19:32 - t-oster

Status:	Closed	Start date:	2012-09-29
Priority:	Normal	Due date:	
Assignee:	peter	% Done:	0%
Category:	firmware	Estimated time:	0.00 hour
Target version:			
Description			
<p>When engraving with VisiCut and the latest LAOS firmware (from github), I get random artifacts in the images. I don't think the problem is in VisiCut's code, because the artifacts seem to be different even if I send the same file again.</p> <p>Has anyone else tried the bitmap-engraving yet?</p> <p>cheers</p> <p>T</p>			

History

#1 - 2012-10-01 21:34 - peter

- Assignee set to peter

#2 - 2012-12-29 16:39 - peter

- Status changed from New to Resolved

Bitmap marking power setting confirmed to work with this test script:

<https://raw.githubusercontent.com/LaosLaser/Software/master/lu/bitmaptest.lua>

There was a bug that caused bitmap data to be corrupted (last word of the data was not engraved). This is fixed in latest GIT commit of the firmware.

#3 - 2012-12-31 14:48 - t-oster

- Status changed from Resolved to Closed

I tried bitmap-engraving with the latest git firmware and have no problems to report.

Files

laosbitmap.jpg	233 KB	2012-09-29	t-oster
----------------	--------	------------	---------