

LAOS Laser - Bug #59

Engraving image does not obey power settings

2012-11-24 16:32 - jaap

Status:	Closed	Start date:	2012-11-24
Priority:	Normal	Due date:	
Assignee:	peter	% Done:	0%
Category:	firmware	Estimated time:	0.00 hour
Target version:	Firmware version 1.0		
Description			
Power settings in the .lgc file do not seem to influence the output power while engraving images.			

History

#1 - 2012-12-29 16:41 - peter

- Status changed from New to Closed

Seems to work OK. Tested with this script:

<https://raw.githubusercontent.com/LaosLaser/Software/master/lua/bitmaptest.lua>