

## Issues

| #  | Project    | Tracker | Status | Priority | Subject  | Assignee | Updated          | Category |
|----|------------|---------|--------|----------|--|----------|------------------|----------|
| 91 | LAOS Laser | Bug     | Closed | Normal   | Decide for one Bugtracker                        |          | 2014-08-17 17:39 |          |
| 67 | LAOS Laser | Feature | Closed | High     | Move away from TFTP                              |          | 2014-08-17 17:41 | firmware |
| 63 | LAOS Laser | Bug     | Closed | High     | First power and Speed setting seem to be ignored | peter    | 2012-12-31 11:57 | firmware |
| 47 | LAOS Laser | Bug     | Closed | Normal   | Random artifacts on bitmap jobs                  | peter    | 2012-12-31 14:48 | firmware |
| 46 | LAOS Laser | Feature | Closed | High     | Make the Z-Axis move synchronously               |          | 2014-08-17 20:41 | firmware |