Issues

| # | Project | Tracker | Status | Priority | Subject | Assignee | Updated | Category |
|----|------------|---------|----------|----------|---|----------|------------------|------------|
| 19 | LAOS Laser | Feature | Closed | Low | Laser on time logging | | 2014-08-17 21:09 | firmware |
| 18 | LAOS Laser | Feature | Closed | Normal | Add hard/soft limits for axes | | 2014-08-17 17:47 | firmware |
| 24 | LAOS Laser | Bug | Rejected | Normal | Laser PWM doesn't seem to be working at all | | 2012-08-13 21:58 | firmware |
| 36 | LAOS Laser | Bug | Closed | Normal | Laser power varies within job | peter | 2014-08-17 17:47 | firmware |
| 62 | LAOS Laser | Bug | Closed | Normal | Menu move moves past machine limits | peter | 2014-08-17 17:46 | I2CDisplay |

2025-05-17